

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	1	("5541510").PN.	USPAT; USOCR	OR	OFF	2005/09/02 16:53
S2	1606	eddy and pulse and (quadratic or polynomial or curve)	USPAT	OR	OFF	2005/09/02 17:25
S3	948	S2 and (ferromagnetic or metal)	USPAT	OR	OFF	2005/09/02 17:26
S4	449	S3 and (parameter or coefficient)	USPAT	OR	OFF	2005/09/02 17:26
S5	40	S4 and (normalize or normalization)	USPAT	OR	OFF	2005/09/02 17:26
S6	160	S4 and non\$linear	USPAT	OR	OFF	2005/09/02 17:07
S7	155	S6 not S5	USPAT	OR	OFF	2005/09/02 17:07
S8	82	S6 and conductivity	USPAT	OR	OFF	2005/09/02 17:27
S9	9	S8 and lift\$loff	USPAT	OR	OFF	2005/09/02 17:27
S10	51	S8 and permeability	USPAT	OR	OFF	2005/09/02 17:27
S11	36438	(sensor or detector) and pulse and (quadratic or polynomial or curve)	USPAT	OR	OFF	2005/09/02 17:29
S12	10091	S11 and (ferromagnetic or metal)	USPAT	OR	OFF	2005/09/02 17:29
S13	4861	S12 and (parameter or coefficient)	USPAT	OR	OFF	2005/09/02 17:30
S14	418	S13 and (normalize or normalization)	USPAT	OR	OFF	2005/09/02 17:26
S15	111	S14 and conductivity	USPAT	OR	OFF	2005/09/02 17:27
S16	0	S15 and lift\$loff	USPAT	OR	OFF	2005/09/02 17:27
S17	14	S15 and permeability	USPAT	OR	OFF	2005/09/02 17:27
S18	2653	(sensor or detector or eddy) and pulse and (polynomial)	USPAT	OR	OFF	2005/09/02 17:29
S19	648	S18 and (ferromagnetic or metal)	USPAT	OR	OFF	2005/09/02 17:29
S20	486	S19 and (parameter or coefficient)	USPAT	OR	OFF	2005/09/02 17:30
S21	303	S20 not fluid	USPAT	OR	OFF	2005/09/02 17:30
S22	272	S21 not coin	USPAT	OR	OFF	2005/09/02 17:30
S23	68	S22 not (optic or optical or laser)	USPAT	OR	OFF	2005/09/02 17:31
S24	51	S23 not human	USPAT	OR	OFF	2005/09/02 17:31